SCIFLEET MOTORS PTY LTD ACN 057 783 749 ABN 25 057 783 749 PO Box 52, LUTWYCHE QLD 4030 Website: scifleettoyota.com.au

Sci-Fleet Toyota

59 Kitchener Rd, KEDRON 4031 Ph : (07) 3361 0077 Fax : (07) 3361 0078

Email: kedron.service@scifleet.com.au

118 Moggill Rd, TARINGA 4068

Ph : (07) 3720 7077 Fax : (07) 3720 7078

Email: taringa.service@scifleet.com.au

BRENDALE

55 South Pine Rd, BRENDALE 4500

Ph : (07) 3862 0977 Fax : (07) 3862 0978

Email: brendale.service@scifleet.com.au

INVOICE #	HA392647 TAX	INVOICE F	R/O # RA270289	Page 1 of 1
Doc. Date 20/01/2021	Customer Name and Address A & M Sgroi	Rego T57904	Stock No. T57904	Adviser JM1
Order No.	107 Bridgeman Road BRIDGEMAN DOWNS QLD 4035	Manufacturer TOYOTA	Kms 10,388	Build Period 01/2020
Customer Code CASHWK	Customer CASHWORK KEDRON	VIN JTFKB8CP406019	794	Delivery Date 00/00/0000
Driver Code		Engine No 1GD86060636	Chassis No	Warranty Date 29/10/2020
Payment	ABN	Model / Series HIACE	Version GD322R	Body Type VAN
Cash Cheque	Contact Ph. (Home) Ph. (Work) 0408804023	Next Service Date 29/10/2021	Date & Time In 20/01/2021 15:45	Body Color
☐ Credit Card ☐ Fleet Card ☐ Account	Ph. (Other) Email:tonysgroi@yahoo.com.au	Next Service Kms 20,000.00	Date & Time Promised 20/01/2021 15:46	Hours Booked 1.20

Product	Description	Quantity	Price
6mth/10,000km ser	vice (TSA \$240)		
LC	SERVICE LABOUR		152.72
	Carried out 6 months/10,000km service, Toyota Service Advantage Plan.		
	Includes:- Replaced engine oil & oil filter.		
	Rotated wheels.		
	Balanced front wheels.		
	Inspected battery electrolyte, cleanliness & security.		
	Inspected air cleaner element.		
	Cleaned air flow meter.		
	Inspected brake fluid.		
	Inspected water sedimenter & drained water trap.		
	Checked power steering fluid.		
	Inspected brake pads & discs.		
	Checked condition & pressures of all tyres including spare.		
	Inspected towbar & nudge bar mounts (if fitted).		
	Inspected all seat belts operation and condition.		
	Checked lights, wiper/washers, horn & electrical systems.		
	Inspected driver's floor mat for correct fitment and retention.		
	Road tested vehicle & reported any defects.	4	0.0
0888800001C	W/WASHER ADDITIVE	1	0.8



TOYOTA KEDRON: 59 Kitchener Rd. 4031 P: (07) 3361 0077 F: (07) 3361 0078

TARINGA: 118 Moggill Rd. 4068 P: (07) 3720 7077 F: (07) 3720 7078

BRENDALE: 55 South Pine Rd, 4500 P: (07) 3862 0977 F: (07) 3862 0978

Postal Address all sites: PO Box 52, LUTWYCHE, QLD, 4030

Continued.....

SCI-FLEET MOTORS PTY LTD ACN 057 783 749 ABN 25 057 783 749

PO Box 52, LUTWYCHE QLD 4030 Website: scifleettoyota.com.au

Sci-Fleet Toyota

KEDRON .

59 Kitchener Rd, KEDRON 4031

Ph : (07) 3361 0077 Fax : (07) 3361 0078 Email: kedron.service@scifleet.com.au

TARINGA

118 Moggill Rd, TARINGA 4068

Ph : (07) 3720 7077 Fax : (07) 3720 7078

Email: taringa.service@scifleet.com.au

BRENDALE

55 South Pine Rd, BRENDALE 4500

Ph : (07) 3862 0977 Fax : (07) 3862 0978 Email: brendale.service@scifleet.com.au

INVOICE #	HA392647	TAX INVOICE	R/O # RA270289	Page	2 of 1
Product 9043012031	Description GASKET	121D		Quantity	Price
90915YZZD2	OIL FILTER 75*8	5 156C		1	21.4
0W30SYNOIL		IC LOW ASH ENGINE OIL		7.5	105.0
М	SHOP SUPPLIES			1	12.5
RE	ENVIRONMENT/F			1	5.9
discadv	TOYOTA ADVAN	TAGE REBATE		1	-82.2
	********** REPOR	T *******			
	GUEST REPORT	S WHEN GOING OVER SPEED BUMPS	ON THE DOWN STROKE, IT		
		HE SUSPENSION IS BOTTOMING OUT			
	TESTED AND CO	ONFIRMED CONCERN IF TRAVELING O	VER 20km/h THE SUSPENSIO	N	
	BOTTOMS OUT I	DUE TO THE ADDITIONAL WEIGHT IN R	EAR (WHEELCHAIR LIFTS)		
	GUEST TO BE A	WARE, CONFIRMED VEHICLE WILL NO	T BOTTOM OUT IF		
	TRAVELLING AT	SPEEDS AT/OR LOWER THAN 15km/H	UNLOADED		
	RECOMMEND A	DJUSTING SPEEDS AS NECESSARY IF	VEHICLE LOADED		

				Sub Total:	218.1

TOYOTA KEDRON: 59 Kitchener Rd. 4031 TARINGA: 118 Moggill Rd. 4068 P: (07) 3361 0077 F: (07) 3361 0078 P: (07) 3720 7077 F: (07) 3720 7078 TARINGA: 118 Moggill Rd. 4068

BRENDALE: 55 South Pine Rd, 4500

P: (07) 3862 0977 F: (07) 3862 0978

Postal Address all sites: PO Box 52, LUTWYCHE, QLD, 4030

24.25
52.72
41.20
0.00
21.81
39.98

SCI-FLEET MOTORS PTY LTD ACN 057 783 749 ABN 25 057 783 749 PO Box 52, LUTWYCHE QLD 4030 Website: scifleettoyota.com.au



KEDRON

59 Kitchener Rd, KEDRON 4031

Ph : (07) 3361 0077 Fax : (07) 3361 0078

Email: kedron.service@scifleet.com.au

TARINGA

118 Moggill Rd, TARINGA 4068

Ph : (07) 3720 7077
Fax : (07) 3720 7078
Email: taringa.service@scifleet.com.au

BRENDALE

55 South Pine Rd, BRENDALE 4500 Ph : (07) 3862 0977 Fax : (07) 3862 0978

Email: brendale.service@scifleet.com.au

INVOICE #	HA400936		TAX INV	OICE R	R/O # RA276570	Page 1 of 2
Doc. Date 31/03/2021	Customer Name and Address A & M Sgroi			Rego T57904	Stock No. T57904	Adviser ES
Order No.	107 Bridgeman Road BRIDGEMAN DOWNS	QLD	4035	Manufacturer TOYOTA	Kms 20,061	Build Period 01/2020
Customer Code CASHWK	Customer CASHWORK KEDRON	Ann		VIN JTFKB8CP4060197	794	Delivery Date 00/00/0000
Driver Code				Engine No 1GD86060636	Chassis No	Warranty Date 29/10/2020
Payment Payment	ABN			Model / Series HIACE	Version GD322R	Body Type VAN
Cash Cheque	Contact Ph. (Home) Ph. (Work) 04	08804023		Next Service Date 30/09/2021	Date & Time In 31/03/2021 13:35	Body Color
☐ Credit Card ☐ Fleet Card ☐ Account	Ph. (Other) Email:tonysgroi@yahoo.com.au			Next Service Kms 30,000.00	Date & Time Promised 31/03/2021 16:00	Hours Booked 1.60

Product	Description	Quantity	Price
12mth/20,000km se	ervice		
LC	SERVICE LABOUR		203.63
	Carried out 12 months/20,000km service as per handbook.		
	Includes:- Replaced engine oil & oil filter.		
	Inspected battery electrolyte, cleanliness & security.		
	Inspected air cleaner element.		
	Cleaned air flow meter.		
	Inspected brake fluid.		
	Inspected water sedimenter & drained water trap.		
	Checked power steering fluid.		
	Inspected brake pads & discs.		
	Checked brake pipes & hoses.		
	Checked exhaust system for security & leaks.		
	Inspected ball joints & dust covers.		
RE	ENVIRONMENT/RECYCLING	1	5.9
	Inspected steering wheel, gear & linkages.		
	Lubricated propeller shaft.		
	Tightened propeller shaft bolts.		
	Inspected rear differential oil.		
	Checked condition & pressures of all tyres including spare.		

TOYOTA KEDRON: 59 Kitchener Rd. 4031

TARINGA: 118 Moggill Rd. 4068 P: (07) 3361 0077 F: (07) 3361 0078 P: (07) 3720 7077 F: (07) 3720 7078

BRENDALE: 55 South Pine Rd, 4500 P: (07) 3862 0977 F: (07) 3862 0978

Postal Address all sites: PO Box 52, LUTWYCHE, QLD, 4030

Continued.....

SCI-FLEET MOTORS PTY LTD ACN 057 783 749 ABN 25 057 783 749

PO Box 52, LUTWYCHE QLD 4030 Website: scifleettoyota.com.au



KEDRON

59 Kitchener Rd, KEDRON 4031 Ph : (07) 3361 0077 Fax : (07) 3361 0078

Email: kedron.service@scifleet.com.au

TARINGA

118 Moggill Rd, TARINGA 4068

Ph : (07) 3720 7077 Fax : (07) 3720 7078

Email: taringa.service@scifleet.com.au

BRENDALE

55 South Pine Rd, BRENDALE 4500 Ph : (07) 3862 0977 Fax : (07) 3862 0978

Email: brendale.service@scifleet.com.au

INVOICE #	HA400936	TAX INVOICE	R/O # RA276570	Page 2	2 of 2
Product	Description			Quantity	Price
Toudot	Rotated wheels.			—	
	Balanced front wheels.				
	Inspected towbar & nud	ge bar mounts (if fitted).			
	Checked brake pedal he	eight & hand brake lever operation.			
		operation and condition.			
	Checked lights, wiper/w	ashers, horn & electrical systems.			
	Inspected driver's floor r	mat for correct fitment and retention			
	Road tested vehicle & re	eported any defects.			
0888800001C	W/WASHER ADDITIVE			1	0.8
1215710010	GASKET, DRAIN PLUG	G 121D		1	1.6
9043012031	GASKET 12	1D		1	1.9
90915YZZD2	OIL FILTER 75*85	156C		1	21.4
М	SHOP SUPPLIES			1	12.5
0W30SYNOIL	0W-30 SYNTHETIC LO	W ASH ENGINE OIL		7.2	100.8
DISCADV	TOYOTA ADVANTAGE	REBATE		1	-130.5
	****** REPORT *****	****			
	NEXT SERVICE DUE 3	0/09/21 OR 30,000KM - WHICHEV	ER OCCURS FIRST.		
	TESTED BATTERY - A	LL OK.			

	NOTES				

	* CARRIED OUT A CO	MPLIMENTARY SAT NAV UPDATE	E TO THE LATEST SOFTWARE		
	* RESET OIL MAINTEN	NANCE REMINDER IN AUDIO UNI	т.		
		NENTLY TURN OFF LANE ASSIST	T. THIS REQUIRES TURNING		
		STICKING OF THE BRAKE PEDAL			

TOYOTA KEDRON: 59 Kitchener Rd. 4031

P: (07) 3361 0077 F: (07) 3361 0078 P: (07) 3720 7077 F: (07) 3720 7078

TARINGA: 118 Moggill Rd. 4068

BRENDALE: 55 South Pine Rd, 4500 P: (07) 3862 0977 F: (07) 3862 0978

Postal Address all sites: PO Box 52, LUTWYCHE, QLD, 4030

Continued.....

SCI-FLEET MOTORS PTY LTD ACN 057 783 749 ABN 25 057 783 749

PO Box 52, LUTWYCHE QLD 4030 Website: scifleettoyota.com.au



KEDRON

59 Kitchener Rd, KEDRON 4031 Ph : (07) 3361 0077 Fax : (07) 3361 0078

Email: kedron.service@scifleet.com.au

118 Moggill Rd, TARINGA 4068

Ph : (07) 3720 7077 Fax : (07) 3720 7078

Email: taringa.service@scifleet.com.au

BRENDALE

55 South Pine Rd, BRENDALE 4500

Ph : (07) 3862 0977 Fax : (07) 3862 0978

Email: brendale.service@scifleet.com.au

NVOICE #	HA400936	TAX INVOICE	R/O # R	A276570	Page 2	2 of 2
Product	Description BRAKE PEDAL BU PEDAL IS APPLIE	T IMMEDIATELY WILL DEACTIVATE TO	WHEN THE ACCELE		antity	Price
			O STOCK.			
	TAKEN PHOTOS (WARRANTY.	ST CONCERN OF DRIVERS FOOT REDF THE AFFECTED AREA AND WILL SONTACTED AS SOON AS WE HEAR	SUBMIT THEM TO TO			
				Sub	Total:	218.1

TOYOTA KEDRON: 59 Kitchener Rd. 4031 P: (07) 3361 0077 F: (07) 3361 0078

TARINGA: 118 Moggill Rd. 4068 P: (07) 3720 7077 F: (07) 3720 7078

BRENDALE: 55 South Pine Rd, 4500 P: (07) 3862 0977 F: (07) 3862 0978

203.63 Labour: -11.34 Others: Rounding: 0.00 21.82 **Total GST:** Total: 240.00

25.89

Parts:

Postal Address all sites: PO Box 52, LUTWYCHE, QLD, 4030