



Ansell Electrical & Air Pty Ltd
+61 466 889 844
info@ansellelec.com
www.ansellelec.com
ABN: 89 641 755 508
Electrical Licence # 86948

Tax Invoice
2173S
10/11/2021

Oxley Outlook Townhouses
86 Jutland St, Oxley QLD 4075

WORK COMPLETED: Please note our new Company ABN and bank details

UNIT 9

Call out to Haier in downstairs Ac error message.
After diagnosis found main board and power module board blown due to a Geckos shorting out the board.
Upon arrival and lifting the lid off the outdoor unit more geckos were found in the unit on the board.

Replace unit with 3.5kw Mitsubishi Electric \$1,525+ If available at time of accepting as supplies for Mitsubishi Electric are currently low.

Supplied and Installed Mitsubishi Electric 3.5kw to replace faulty unit. Test and all working.

DESCRIPTION	QTY	UNIT PRICE	TOTAL PRICE
Replace unit with 3.5kw Mitsubishi Electric \$1,525+	1	\$1,525.00	\$1,525.00
Upstairs unit service and clean	1	\$40.00	\$40.00
		SUBTOTAL:	\$1,565.00
		GST:	\$156.50
		TOTAL:	\$1,721.50
		PAID:	\$0.00
		BALANCE DUE:	\$1,721.50

How to Pay

Tax Invoice # 2173S
\$1,721.50 due by **17th November 2021**

We accept payment by: Bank Deposit, Card or Cash

Bank Details Ansell Electrical & Air Pty Ltd
BSB: 064 173
Account Number: 1076 0228

Online payment Visit this link to pay your invoice online: <https://sm8.link/fevnyyh>

For electrical installations, this certifies that the electrical installation, to the extent it is affected by the electrical work, has been tested to ensure that it is electrically safe and is in accordance with the requirements of the wiring rules and other standards applying under the Electrical Safety Regulations 2002 to the electrical installation.
For electrical equipment, this certifies that the electrical equipment, to the extent it is affected by the electrical work, is electrically safe.