

P. (02) 8373 1113 F. (02) 8373 1112

E. mark@mhcarpets.com.au W. www.mhcarpets.com.au

785 Pittwater Road Dee Why, NSW 2099

ABN. 51 137 355 750

## CONTRACT AGREEMENT & TAX INVOICE NO. 0026867 20/06/2018

Date.

Fax.

Salesperson. VL

Installation Date.

28/06/2018

**;LIENT** 

MCGEADY FAMILY SUPER TRUST

SITE: 203/30 FISHER RD DEE WHY NSW 2099

INSTALLATION

ADMIN@NBCONSULTING.COM.AU (JODIE)

**ADDRESS** Phone No. Mbl. 0409 125 465 (DAVE) Hm.

colin@nbconsulting.com.au G/HIRST NEWPORT COL: CHARCOAL

TO SUPPLY TYPE OF UNDERLAY EXCELLAY COMMERCIAL FOAM

INSTALLATION METHOD

STANDARD LAYING

TAKE UP 1

TO SUPPLY

26/06 - IN WAREHOUSE (JK)

TAKE UP 2	NIL OR CLIENT TO SHIFT ALL FURNITURE	STAIRS Boxed 0 Winders 0 Wraps 0 B-Nose 0
FURNITURE Std. Trim Mtrs.Trim	0 Std. Nap 0 Std. Multi 0 Mtrs. Nap 0 Mtrs. Multi	0 Trim details

Bus.

TO SUPPLY AND INSTALL NEWPORT COL CHARCOAL CARPET OVER COMMERCIAL UNDERLAY IN

OFFICE AREA FOR THE TOTAL AMOUNT OF ......\$3,995.00

THE ABOVE QUOTATION INCLUDES TAKE UP AND DISPOSAL OF EXISTING FLOORCOVERINGS , EXTRA

SMOOTHEDGE AS REQUIRED AND GST

( v BEST PRICE IS \$3900 INC GST

ONLY 9 M IN STOCK ATM IN TRANSIT DUE 16 DAYS - BONNIE (AR)

ONLY 9 M IN STOCK ATM IN TRANSIT DUE 16 DAYS - BONNIE (ATT)  22/06 - ORDERED REF# 2296012 WITH JACQUI (JK) ON TRUCK 25/6 (KATIE)  ***********************************			
Deposits are considered as an Authorization to proceed on your behavior.  Mark Henderson's Carpets cannot be held responsible for delays caused by manufacturing, transport.	GST Total Sale	\$ \$	354.55 3900.00
Our installers will, if pre-arranged, move furniture which has been emptied prior to their arrival.  Our installers will, if pre-arranged, move furniture which has been emptied prior to their arrival.  Any sub-floor preparation will be at the client's expense unless detailed in the quote  Any sub-floor preparation will be at the client's expense unless detailed in the quote  N.B. Old underlay can sometimes be stuck to the floor which will incur an additional charge.  N.B. Old underlay can sometimes be stuck to the floor which will incur an additional charge.	22/06/2 V	\$	1950.00
Direct Deposit Mark Hendersons Carpets BSB 012 243 AC 110 2040 CUSTOMER NAME/SIGNATURE (Authorise to proceed)	Bal Due	\$	1950.0