

## VALUATION REPORT INDUSTRIAL PROPERTY



### 1/25 ONSLOW AVENUE, CAMPBELLFIELD VIC 3061

As At

## 12<sup>th</sup> DAY OF FEBRUARY 2019

Prepared for:

# E & H CHRISTIE PTY LTD ATF CHRISTIE SUPERANNUATION FUND

Chris Mason & Associates Pty Ltd ABN 850 116 691 10 P.O. Box 1287 Doncaster East VIC 3109 T: 0417 741 481



# **Industrial Valuation Report**

Prepared For: E	& H Christie Pty			Em	ail Address:	Helen	C@brimbank.		
		istie Superannuation Fund			all Autross.	1000		VIC.gov.au	
Address: 1/	25 Onslow Aver	Onslow Avenue,							
	ampbellfield Vic		an to physical	· increat the cul		arty and provid			
in	dependent assess	ment of the cur	n to physically inspect the subject property and provide our the property as at the date of our inspection, assuming the						
		erty had been notionally offered for sale in the prevailing market conditions. This valuation has been prepared for can be relied upon for self managed super fund annual reporting purposes.							
ui			ayeu super runa ar		j puiposos.				
1. PROPERTY SUMMAR	Y – Industria	I Factory /	Warehouse						
PROPERTY ADDRESS	1/25 Onslow	Avenue, Can	npbellfield Vic 30	61					
TITLE DETAILS		Volume 09764 Folios 818, being Unit 1 on Strata Plan No. 026830.							
<b>Registered Proprietors</b>	Christie E &	Christie E & A Pty Ltd as sole proprietor.							
Encumbrances/Restr'ns	: Mortgage Al	Mortgage AL07167AH dated 09/05/2014 in favour or Westpac.							
Site Dimensions	: Irregular	Irregular			Site Area:	425.0	sqm		
ZONING/INSTRUMENT	: "Industrial 3"	"Industrial 3" Zone / Hume Planning Scheme			LGA:	City of	Hume		
MAIN BUILDING	: Semi detach	Semi detached factory / warehouse			Current Use:	Factor	y / warehous	Э	
Built About	: 1987	1987 <b>Addition(s):</b>				N/A			
TOTAL AREAS	Gross Buildi	Gross Building Area: 312.10 sqm (Ground Floor 280.9 sqm & Mezzanine Floor 31.2 sqm)							
CAR ACCOMMODATION		arspaces							
MARKETABILITY	0	Average		Heritage Issues:		N/A			
ENVIRONMENTAL ISSUES	None			Essen	tial Repairs:	None			
2. RISK ANALYSIS									
Property Risk Rating	6 -		+ N	larket Risk I	Ratings	-		+	
Location & Neighbourhood		Neu	Market Demand:			Neu			
Land Area	:	Neu Saleability:		eability:		Neu			
Improvements		Neu	Market Direction:			Neu			
			2 = Low to Mediu	m, 3 = Mediu	um, 4* = Mediu	um to Hi	gh, 5* = High		
3. VALUATION & ASSES									
Interest Valued	: Fee Simple	vacant posses	sion	Other Asse	essments				
Value Component	Strata Pr	operty		Market	Rental \$21,	850 pa,	plus GST & C	D/G	
Units	:	2		Ins	urance Owr	ers Cor	poration Resp	onsibility	
Entitlements	: 100	Out of:	200						
Current Market Value	:	\$415,000	(Exclusive of C	GST)					
Rec. Documents to Sight		alow and have some					is firm has any assi	list of interact or	
I hereby certify that I personally inspected thi direct, indirect or financial interest in relation	to this property that is n	ot disclosed herein.							
This report is for the use only of the party to a does not constitute a structural survey.	which it is addressed an	d is not to be used fo	r any other purpose. No	responsibility is ac	cepted or undertaken	to third part	ies in respect thereo	f. This report	
Valuer	Chris Ma	Chris Mason			Firm: Chris Mason & Associates Pty Ltd				
Qualifications				Address:	P.O. Box 1287	, Doncaster East VIC 3109			
Inspection Date	: 12/02/2019			Phone:	0417 741 481				
Valuation Date	: 12/02/2019			Email: <u>chris@masonre.com.au</u>					
Signature	Ohin M	65-441							



4. THE LAND								
Property Identification:	This property has been identified by reference to its street address and title search.							
Has Title Been Searched:	Yes							
ZONING EFFECT:	An industrial use of the property is considered a permissible under the current zoning.							
LOCATION: NEIGHBOURHOOD:	The subject property comprises one of two semi-detached factory / warehouses which are located along the western alignment of Onslow Avenue at is northern end within the established, northern suburb of Campbellfield. The property forms part of an established industrial pocket which is located between Sydney Road and where Mahoneys Road crosses the Western Ring Road. The property is located within an area which is dominated by the Broadmeadows Motorcycle Park and the Campbellfield Landfill Centre which are both located to the north of the property. The property is located within an area, which is well serviced by a range of key arterial road linkages. The property is located approximately 13.8 radial kilometres to the north of the Melbourne GPO.							
SITE DESCRIPTION & ACCESS:	One of two factory / warehouses sited upon a regular shaped allotment with shared driveway.							
SERVICES:	All essential services are available to the property.							
	All essential services are available to the property.							
5. BUILDING		-						
5. BUILDING Style:	1980's semi detached factory / warehouse Street Appeal:	Average						
5. BUILDING Style: Main Walls & Roof:	1980's semi detached factory / warehouse Street Appeal:   Brick walls and metal roof Window Frames:	Aluminum						
5. BUILDING Style: Main Walls & Roof: Main Interior Linings:	1980's semi detached factory / warehouse Brick walls and metal roof Exposed brick and plasterboardStreet Appeal: Window Frames: Flooring:	Aluminum Concrete & timber						
5. BUILDING Style: Main Walls & Roof: Main Interior Linings: Internal Condition:	1980's semi detached factory / warehouse Brick walls and metal roof Exposed brick and plasterboard AverageStreet Appeal: Window Frames: Flooring: External Condition:	Aluminum Concrete & timber Average						
5. BUILDING Style: Main Walls & Roof: Main Interior Linings:	1980's semi detached factory / warehouse Brick walls and metal roof Exposed brick and plasterboardStreet Appeal: Window Frames: Flooring:	Aluminum Concrete & timber Average						
5. BUILDING Style: Main Walls & Roof: Main Interior Linings: Internal Condition:	1980's semi detached factory / warehouse Street Appeal:   Brick walls and metal roof Window Frames:   Exposed brick and plasterboard Flooring:   Average External Condition:   Entry, open plan factory / warehouse space, office / lunchroom, exit, m	Aluminum Concrete & timber Average						
5. BUILDING Style: Main Walls & Roof: Main Interior Linings: Internal Condition: Accommodation:	1980's semi detached factory / warehouse Street Appeal:   Brick walls and metal roof Window Frames:   Exposed brick and plasterboard Flooring:   Average External Condition:   Entry, open plan factory / warehouse space, office / lunchroom, exit, n kitchenette and male and female toilets.	Aluminum Concrete & timber Average nezzanine storage space, rear						
5. BUILDING Style: Main Walls & Roof: Main Interior Linings: Internal Condition: Accommodation: Interior Layout:	1980's semi detached factory / warehouse Street Appeal:   Brick walls and metal roof Window Frames:   Exposed brick and plasterboard Flooring:   Average External Condition:   Entry, open plan factory / warehouse space, office / lunchroom, exit, n kitchenette and male and female toilets.   Conventional style factory / warehouse. Street Appeal:	Aluminum Concrete & timber Average nezzanine storage space, rear x air conditioner to the office /						

AREAS: CAR ACCOMMODATION:

#### 6. ANCILLARY IMPROVEMENTS

Shared concrete driveway, 6 x open air carspaces and cyclone wire fencing and front gates.

6 x open air carspaces

#### 7. OCCUPANCY

We note that the property is presently owner occupied at this time.

# 8. SALES EVIDENCE & THE MARKET

Address	Sale Date / \$ Price	Brief Comments	Sale Image
1/32 Onslow Av, Campbellfield	Dec 2017 / \$415,000	The sale comprised a strata titled factory / warehouse unit, being one of 4 on the block The property is improved with an established single storey concrete panel factory / warehouse building, having an area of 254.0 sqm and a further mezzanine of 122.0 sqm. In addition the property included 3 carspaces. The property was sold fully let.	
3A Colbert Rd, Campbellfield	Mar 2018 / \$415,000	The sale comprised a strata titled, factory / warehouse unit, being one of two on a block. The property is improved with an established, single storey brick factory / warehouse building, having an area of approximately 288.0 sqm. The property was sold with vacant possession	
8/50 Camp Rd, Broadmeadows	July 2018 / \$440,000	The sale comprised a strata titled factory / warehouse unit, being one of 14 on the block. The property is improved with an established single storey concrete panel factory / warehouse building, having an area of 232.0 sqm. In addition the property included 4 carspaces. The property was sold vacant.	
67 Horne St, Campbellfield	Oct 2018 \$570,000	The sale comprised a regular shaped, near level, inside allotment of industrial land, encompassed within a similar Industrial 3 zoning, with a land area of 855.0 sqm. The property was improved with a large, clearspan, metal clad factory / warehouse with small office area. The property also included onside parking for 5 cars. The property was sold with vacant possession.	
Previous	Sale of the Proper	ty: 10/03/2014 - \$350,000	
Lev	el of Market Activi	ty: Steady Recent Market Direction:	Steady

# MASON'S

# **Industrial Valuation Report**

#### 9. ADDITIONAL COMMENTS

#### The Property:

The subject property comprises an established, single storey factory / warehouse unit, being one of two on a block, having a shared driveway from Onslow Avenue. The property is encompassed within an Industrial 3 zoning and has its own land area of approximately 425.0 square metres.

The property is improved with an established, semi-detached, brick clad factory / warehouse building constructed circa 1987. Accommodation includes Entry, open plan factory / warehouse space, office / lunchroom, exit, mezzanine storage space, rear kitchenette and male and female toilets. Internally the property provides an average standard of factory / warehouse accommodation having a building area of approximately 312.10 square metres. As at the date of inspection the property was in good overall condition.

#### Sales Evidence:

In determining our assessment as to the current market value of the property, we have reviewed a range of other recent factory/warehouse sales within the Campbellfield area over the last 12 months or so. We have assessed the current market value of the property based upon on a selling period which typically might be up to 3 months.

The most comparable sales have been summarized within our sales evidence section of this report. The sales provide a broad range of between \$415,000 at the lower end of the range and \$570,000 at the upper end of the range. The sales equate to a comparative range of between \$1,104 and \$1,897 on a per square metre of lettable area basis.

#### Valuation Conclusion:

Taking into account all of the attributes of the property including its location, their age and standard of the accommodation provided by the improvements and in contrast to the comparable sales evidence prevailing in the market place today. We have for the purpose of this valuation, assessed the current market value for the property as at the date of valuation the 12<sup>th</sup> February, 2019 at \$415,000.

#### **10. CLIENT-SPECIFIC INFORMATION**

I have made all inquiries that I consider to be necessary and appropriate and to my knowledge, there have not been any relevant matters omitted from this report except as otherwise specifically stated within this report. I believe that the facts within my knowledge that have been stated in this report are true. The opinions I have expressed in this report are independent and impartial. I have complied with the requirements of the following professional codes of conduct or protocol, being the Australian Property Institute code of Professional Practice Standards 2009. I certify to being a current and paid up member of the Australian Valuers Institute (AVI) and have been a Certified Practicing Valuer since 2001. This valuation is current as at the date of valuation only. The value assessed herein may change significantly and unexpectedly over a relatively short period (including as a result of general market movements and factors specific to the particular property). We do not accept liability for losses arising from such subsequent changes in value. Without limiting the generality of the above comment, we do not assume any responsibility or accept any liability where this valuation is relied upon after the expiration of 3 months from the date of the valuation, or such earlier date if you become aware of any factors that have any effect on the valuation.



# Industrial Valuation Report

#### **11. DIGITAL IMAGES**



1/25 Onslow Av, Campbellfield – 'the property'



**Factory Internal** 



Mezzanine Area



Bathroom



Office / Lunchroom



Factory Internal



**Kitchenette (rear)** 



Carpark



## **Industrial Valuation Report**

